TABULATION SUMMARY Conroe ISD

CSP #33-004-Kitchen Equipment Repairs & Preventative Maintenance

Commodity #146 Expires February 28, 2016

Awarded Vendors are highlighted

		Section I				Section II		
Award Status	Bidder	Hourly Labor Rate 8AM - 5PM	Hourly Labor Rate after 5/ weekends	Service Call Charge	Manufacturer Discount for Parts	# of Low bids Hot Repair Scenarios	# of Low bids Refrigerated Repair Scenarios	
Primary	Werner Refrigeration	\$73.50	\$110.25	\$36.75	12%	3	3	
Secondary	Secondary My Tech Texas \$70.00		\$105.00	\$68.60	30-50%	2	1	
	Coolers Inc.	\$85.00	\$127.50	\$30.00	3-10%	0	1	
	Dawson Co	\$75.00	\$112.50	\$75.00	10%	0	n/a	
	GCS Services dba EcolabEquip. Care	\$80.00	\$120.00	\$80.00 fuel	5%	0	0	

		Section III			
Aand Otatus	Diddon	Annual Preventative Maintenance			
Award Status	Bidder	Costs			
	GCS Services dba				
Primary	EcolabEquip. Care	\$55,585.50			
	Dawson Co	\$60,602.50 *			
Secondary	Werner Refrigeration	\$67,771.40			
	Coolers Inc.	\$82,800.00			
	My Tech Texas	\$84,800.00			

^{*} Cost for Hot Equipment Repair tasks only. Does not work on refrigerated equipment

CSP #33-004-Kitchen Equipment Repairs & Preventative Maintenance Tabulation - Section II. Market Basket of Repair Scenarios

	Hot Equipment Repair Scenarios	Werner Refrigeration	My Tech Texas	Coolers Inc.	Dawson Co	GCS Services dba Ecolab Equipment Care		
1.	Problem: Disposal (Salvajor 200) not running, motor is humming. Solution: Free obstruction from grinding teeth. Clean lines. Repair time: 1.5 hours during normal business hours							
•	Labor 1.5 h		\$105.00		\$112.50			
	Materials	,						
	Service Call	\$36.75	\$68.60		\$75.00			
	Total Cost	\$147.00	\$173.60	N/A	\$187.50	\$200.00		
	Problem: Dishwasher (Hobart AM 14) is leaking. Solution: Replace drain line, order o-ring for drain pipe, repair leak at drain fitting, clean floats and probes, and rinse nozzles. Repair Time: 2 hours - after hours							
	Labor 2 h	r \$220.50	\$210.00		\$225.00			
	Materials	\$79.01	\$25.00		\$28.60			
	Service Call	\$36.75	\$68.60		\$112.50			
	Total Cost	\$336.26	\$303.60	N/A	\$366.10	\$440.00		
	Solution: Reset points for heat and time. Reloc Adjust and tighten gears drive on right hand ove Repair Time: 1.5 hours during normal business Labor 1.5 h	en. Adjust speed and tem hours		\$127.50	\$150.00			
	Materials	*	4	*				
	Service Call	\$36.75	\$68.60	\$30.00	\$75.00			
	Total Cost	\$147.00	\$173.60	\$157.50	\$225.00	\$200.00		
	 Problem: Steamer (Cleveland 24CGA10) is leaking. Solution: Order fitting and float switch chase, replace bad fill valve, and unstop drain valve. Replace condensated solenoid and order fill valve. Clean scale deposits and drain lines. Repair Time: 2 hours during normal business hours 							
	Labor 2 h	r \$147.00	\$140.00		\$150.00			
	Materials	\$387.10	\$75.00		\$231.85			
	Service Call	\$36.75	\$68.60		\$75.00			
	Total Cost	\$570.85	\$283.60	N/A	\$456.85	\$770.00		
	5. Problem: Conveyor oven (Lincoln) not working properly. Solution: Adjust gas pressure and air shutter located on burner. Repair Time: 1 hour during normal business hours							
	Labor 1 h		\$70.00	\$85.00	\$75.00			
	Materials				•			
	Service Call	\$36.75	\$68.60	\$30.00	\$75.00			
	Total Cost	\$110.25	\$138.60	\$115.00	\$150.00	\$160.00		
	(out of 5 possible)							
	out of 5 repair scenarios	3	2	0	0	0		

Refrigerated Equip	ment Repair Scenar	ios	Werner Refrigeration	My Tech Texas	Coolers Inc.	Dawson Co	GCS Services dba Ecolab Equipment Care
6. Problem: Beverage	Air BZ 13 (#2406x13	843) le	•				
condenser and eva	condenser and evaporator. Replace skid and monitor for proper temperatures.						
Repair Time: 1.5 hor	urs during normal bus	siness h	nours				
	Labor	1.5 hr	\$110.25	\$105.00	\$127.50		
	Materials		\$29.99	\$25.00			
	Service Call		\$36.75	\$68.60	\$30.00		
	other				\$15.00 nitrogen charge		
	Total Cost		\$176.99	\$198.60	\$172.50	N/A	\$212.00
Solution: Found mu door sweep and gas	Problem: Walk-In cooler (Heatcraft Equip.) coil freezing up. Solution: Found multiple outdoor air leaks, refrigerant and electrical line penetrations, door sweep and gaskets worn. Sealed leaks, replaced gaskets, sweep thawed coil. Repair Time: 2 hours during normal business hours						
	Labor	2 hr	\$147.00	\$140.00	\$170.00		
	Materials		\$155.00	\$135.00	\$256.62		
	Service Call		\$36.75	\$68.60	\$30.00		
					\$25.00 torch charge		
	Total Cost		\$338.75	\$343.60	\$481.62	N/A	\$423.00
Repair Time: 1.5 hou	Labor Materials Service Call	1.5 hr	\$183.75 \$6.00 \$36.75	\$157.50 \$10.00 \$68.60	\$191.25 \$10.00 \$30.00		
	other Total Cost		\$226.50	\$236.10	\$231.25	N/A	\$310.00
Solution: Found dirt	Problem: Traulsen Reach-in Cooler (#RH132WP-X0097) at 55° Solution: Found dirty condenser coil. Cleaned coil and checked IntelaTraul settings. Repair Time: 1.5 hours during normal business hours						
	Labor	1.5 hr	\$110.25	\$105.00	\$127.50		
	Materials			\$25.00			
	Service Call		\$36.75	\$68.60	\$30.00		
			\$6.00		15.00 nitrogen		
	Total Cost		\$153.00	\$198.60	\$172.50	N/A	\$200.00
 Problem: Manitowoo Solution: found eval Repair Time: 4 hours 	porator pitted. Replac	,	•				
Aopail Tille. 4 Hours	Labor	4 hr	\$441.00	\$420.00	\$510.00		
	Materials	7 111	\$1,418.75	\$1,100.00	\$1,463.70		
	Service Call		\$36.75	\$68.60	\$30.00		
	ocivide dan		ψου.7 σ	\$45.00 EPA/Weld	\$25.00 weld charge \$20.00 recovery		
	Total Cost		\$1,896.50	\$1,633.60	\$2,048.70	N/A	\$1,977.00
Number of low -	Cold Repair						
(out of 5 possib			3	1	1	N/A	0